




The wooden covered bridge, previous page, in the process of being razed after the locomotive fell through the left hand side of the bridge.



"Dinky in the drink" as this photo is often labeled. The engine was brought right side up and a ramp of temporary track was built to pull it back onto the grade. The wooden bridge was replaced by a steel bridge.